

GREENVILLE UTILITIES COMMISSION
QUESTIONS AND ANSWERS II FOR 23-64
RFB FOR TUBULAR STEEL STRUCTURES
1/11/2024 at 2:00PM

1. We appear to be missing the information described in Item #6 on the RFI: *The minimum base plate thickness, per preliminary designs, are located in the Bid Attachment provided in the RFB, in the second column from the left.* Please request the customer to provide this information ASAP. We can make assumptions without it, but it's always best to work with complete information.

Please see Attachment A attached. The second column from the right has the information they requested and it is the caisson thickness, not base plate thickness.